



Shielded Red To ECU
Tach Output
Blue / Screen Not Used



Blue/Yellow To ECU
TPS Input
The TPS must be connected to the ECU

Gotech Gear X Ecu




14 Pin Plug		16 Pin Plug	
1 Orange	3v Out	1	
2		2	
3 Brown/White	Common E	3	
4		4	
5 Green	Shift Down	5	
6 Blue/Yellow	TPS	6	
7		7	
8		8	
9		9 Brown	Earth
10 Red	RPM In	10	
11 Blue	A/M SW	11 White/Green	Lockup
12 Yellow	Shift Up	12	
13		13 Red/White	Solenoid 2
14		14 Black/White	Solenoid 1




15 Black	Power 12v+
16 Black	Power 12v+



Relay 1	Relay 2	Relay 3
85 - Ign +	85 - Ign +	85 - Ign +
86 - Gotech Pin 14	86 - Gotech Pin 13	86 - Gotech Pin 11
30 - Batt +	30 - Batt +	30 - Batt +
87 - Gearbox Pin 3	87 - Gearbox Pin 6	87 - Gearbox Pin 5



Brown
Gotech Pin 9



Shielded Red To ECU
Tach Output
Blue / Screen Not Used

Blue/Yellow To ECU
TPS Input
The TPS must be connected to the ECU

Gotech Gear X Ecu

14	13	12	11	10	9	8	16	15	14	13	12	11	10	9
7	6	5	4	3	2	1	8	7	6	5	4	3	2	1

14 Pin Plug		16 Pin Plug	
1 Orange	3v Out	1	
2		2	
3 Brown/White	Common E	3	
4		4	
5 Green	Shift Down	5	
6 Blue/Yellow	TPS	6	
7		7	
8		8	
9		9 Brown	Earth
10 Red	RPM In	10	
11 Blue	A/M SW	11 White/Green	Lockup
12 Yellow	Shift Up	12	
13		13 Red/White	Solenoid 2
14		14 Black/White	Solenoid 1
		15 Black	Power 12v+
		16 Black	Power 12v+